SECRET

TAB C - HIGHWAY BRIDGES

Location	Target Number	Name	Date	Status
Route 1A		Dong Hoi Hwy Bridge over	3-4 Apr 65	Initial strikes. 9 spans destroyed or damaged.
172725N 1063745E		Rao Le Ky		Bridge unserviceable.
- 20	25X1	400 x 13 ft.; ll-span, half-thru steel truss on concrete	9 Apr 65	4 destroyed spans cleared for river navigation; construction started on ferry landings adjacent to target bridge.
25X1		piers	14-19 Apr 65	Ferry landings still under construction.
			23 Apr 65	Ferry landings near completion; north ramp 105 x 18 ft, south ramp 200 x 18 ft.
	14		26 Apr 65	No repairs accomplished on target bridge.
				Cratering on approach roads repaired. Ferry landings still under construction; progress slowed up.
			21 May 65	Work on ferry landings suspended. Temporary timber foot bridge under construction over
		* * * * * * * * * * * * * * * * * * * *		destroyed spans on target bridge. Approaches in poor condition.

DIA review(s) completed.

			*		
Location	Target Number	Name	т.	Date	Status
				3 Jun 65	Bridge serviceable. Temporary repairs appear complete; open for foot and cart traffic - 2 months outage.
		- 100	-	3-17 Jun 65	Bridge open to light traffic. Ferry noted in area, 17 June.
			*	19 Jun 65	Bridge unserviceable. 2 spans out - probably washed out.
				26 Jun 65	Bridge serviceable. Temporary spans and approaches repaired - open for light traffic.
				5 Jul 65	Bridge unserviceable. 2 spans collapsed or removed.
				25 Jul 65	Restrike. Bridge unserviceable. 3 mid-stream spans destroyed. South end span severed from abutment. South ferry landing ramp cratered.
				25 Jul - 13 Aug 65	Bridge remains unserviceable. No repairs evident. No ferry operation indicated.
				23 Aug 65	Restrike. 2 remaining spans demolished. Eridge unserviceable. I span further damaged. Both approaches heavily cratered.

Location	Target Number	Name	Date	Status
`			2 Oct 65	No repairs evident. No bypass activity vicinity of the bridge.
			7 Oct 65	Restrike. No further damage reported.
			7 Oct - 24 Dec 65	Eridge remains unserviceable. No restoration.

SECRET

Location	Target Number	Name	Date	Status
Route 1A 181907N 1055504E		Ha Tinh Hwy Bridge over Song Nai	24 Apr 65	Initial strike. Bridge still standing; approache cratered.
20000411	25X1	220 x 15 ft.; 3-span, half-thru steel truss	10 May 65	Restrike. North span dropped, north abutment destroyed. Center span damaged. Ferry approaches severely damaged. Bridge unserviceable.
25X1		9	14 May 65	Ferry facility serviceable; ferry noted.
	•	×	3 Jun 65	Bridge unserviceable.
		*	8-14 Jun 65	No change. Ford serviceable.
	÷		4 Jul 65	Bridge decking removed; ferry in use.
			18-24 Jul 6	5 No change.
	,		12-27 Aug 6	5No change.
			1 Sep 65	No Change.
		. *	4 Sep 65	Restrike. Center span dropped, approaches cratered. No repairs noted.
		i i		

Location	Target Number	Name	Date	Status
			13-2 7 Sep 65	No change. Ferry landings serviceable.
			1 Oct 65	No change.
		•	2 Oct 65	Serviceable foot bridge observed upstream.
			10-26 Oct 65	Bridge unserviceable. Ferry serviceable.
			1-3 Nov 65	No change.
•			7 Nov 65	Approaches cratered. Bypass under construction.
		*	9 Nov 65	Bridge unserviceable. Ferry landings serviceable.

TAB C - HIGHWAY BRIDGES

1	•	LAB C.	HIGHWAY	BRIDGES
Location	Target Number	Name	Date	Status
Route 6		Ban Pa Huone Hwy	23 Jul 65	
214810N 1031828E		Bridge over Nam Meuk		Initial strike. Severe damage to one span; moderate damage to 2 others. Bridge usable for foot traffic only.
	25X1	210 x 10 ft; 4-span, half-thru steel truss	29 Jul 65	Restrike. Three spans dropped; remaining
25X1		and the second		approach heavily cratered. At time of strike, ferry or ford approach ramps were being prepared.
		· · · · · · · · · · · · · · · · · · ·	24 Aug 65	Bridge still unserviceable.
		.0	28 Aug 65	Ferry approach ramps completed. No bridge reconstruction noted; unserviceable.
	· ·		17 Oct 65	Ferry next to bridge site noted. Bridge unserviceable.
	. · ·		19 Oct 65	No change from 17th.
		<i>X</i> .	28 Oct 65	Bridge still out; ponton bridge site approx. 200 yards NE of target.
		•	2-4 Dec 65	Bridge unserviceable; ponton sections under construction just north of ponton bridge site. Ferry observed north of ramps.
				No change since 4 Dec. Bridge unserviceable.
			05005	

SECRET Approved For Release 2002/08/06 : CIA-RDP78S02149R000100170010-1

Approved For Release 2002/08/06 : CIA-RDP78S02149R000100170010-1 \$\frac{\text{SECRET}}{\text{CRET}}\$

Location	Target Number	Name	Date	Status
Route 7		Khe Kien Hwy	9 Apr 65	Initial strike. Three-span structure completely
191621N 1042117E		Bridge West over Nam Kien	-	destroyed; approaches damaged.
104211/15	25X1	340 x 18 ft.; 3-span, deck-type modern reinforced con-	6 May 65	Former bridge replaced by earth embankment (causeway) with small (20 ft.) bridge; serviceable.
25X1		crete haunched T-beam on con- crete piers.	8 Jun 65	Piles of lumber near bridge site, suggesting reconstruction activity.
•			27 Sep 65	Ford just north of former bridge site.
			7 Nov 65	Small bridge destroyed. Two bypass routes with fords constructed.
	•		3 Dec 65	One ford destroyed, another bypass constructed.

<i>:</i>				
Location	Target Number	Name	Date	Status
Route 7 185751N 1053420E		Phuc Thiem Hwy Bridge over stream	23 Apr 65	Initial strike. Bridge demolished along with east abutment. Extensive cratering on both approaches.
25X1	25X1	100 x 15 ft.; 1-span, concrete or masonry arch.	15 May 65	Bridge unserviceable. No reconstruction at bridge site. Road approaches under repair. Probable ferry landing under construction near target. New foot bridge installed north of bridge.
			15 May 65- 16 Jun 65	Bridge remains unserviceable. No new construction noted. Probable ferry operating nearby.
			7 Jul 65	New bridge under construction at original bridge site. Four piers installed.
		*	17 Jul 65	Restrike. Crossing remains unserviceable. Eastern approach heavily cratered. Moderate damage to replacement bridge which now has deck stringers partially installed.
		/	18 Jul 65	Nearby foot bridge also unserviceable.

SECRET

Location	Target Number	Name .	Date	Status
			5 Aug - 31 Aug 65	Crossing remains unserviceable. Construction on replacement bridge apparently halted.
	·	* *	18 Sep 65	Construction on replacement bridge nearly completed and possibly serviceable - 5 month recovery effort.
			27 Sep 65	Restrike. New bridge unserviceable. Bridge superstructure heavily damaged; adjacent foot bridge demolished.
			28 Sep - 27 Oct 65	Bridge remains underviceable. Clearing for ferry landings nearby.
•	, .		6 Nov 65	Ferry craft detected vicinity of bridge.
			16 Nov - 13 Dec 65	Bridge remains unserviceable. No reconstruction attempted. Ferry crossing probably serviceable 100 yards south of target bridge.

SECREL

Location	Target Number	Name	Date	Status
Route 8 182600N 1051325E		Kim Cuong Hwy Bridge S.W. over Nam Chot	10 Apr 65	Initial strike. Center span destroyed, end spans severely damaged; approaches cratered. Bridge unserviceable.
	25V4	165 x 15 ft.; 4-span, concrete beam	10 May 65	Bridge unserviceable; ford serviceable.
	25X1	with concrete deck on concrete piers	28 May 65	Bridge unserviceable but under repair.
25X1		on concrete piers	14-26 Jun 65	No change. Ford serviceable.
	**		2 Jul 65	40% of northeast end has been repaired. Both approaches restored.
* * * * * * * * * * * * * * * * * * *		***	18-22 Jul 65	No change. Ford serviceable.
		9	9-30 Aug 65	No change. Ford serviceable.
	* *		1-4 Sep 65	No change. Ford serviceable.
		. •	19 Sep 65	No change. Ferry appears serviceable.
			23 Sep 65	No change.

Location	Target Number	Name	Date	Status
	•	•	28-30 Oct 65	No change.
			3 Nov 65	Restrike. North approach heavily cratered. Bridge unserviceable: ford serviceable.

SECRET

Location	Target Number	Name	Date	Status
Route 15		Bai Duc Thon Hwy	16 Apr 65	Initial strike. Bridge unserviceable. 3 spans
180405N 1054930E		Bridge over Ngan Sau		effectively destroyed or weakened. Center span destroyed; north span sagging; other span extensively damaged. Roadway at north
	25X1	320 x 16 ft.; 5-span, concrete deck		approach cratered.
25X1	.	type	24 -25 Ap r 65	By-pass in service. Original ford crossing rejustabled with rock lining. Destroyed spans partially repaired on target bridge.
			25-26-27 Apr 65	Hestrike. Bridge unserviceable. Further light damage to bridge. Ford bypass not affected.
			27 Apr - 13 May 65	Ford bypass remains serviceable. No bridge repairs.
		*	3 Jun 65	Ford probably being strengthened with additional rock base.
	. •	· · · · · · · · · · · · · · · · · · ·	3 Jun - 23 Sep 65	Bridge remains unserviceable. Ford in use. Only minor repairs noted.
	*		4 Oct 65	Alternate beidge construction site detected, 1,000 yards north of target bridge. Stone fill approach at north end near completion.

•

TAB C- HIGHWAY BRIDGES

Approved For Release 2002/08/06 : CIA-RDP78S02149R000100170010-1

Location	Target Number	Nama	Date	Status
Route 15		Xom Ca Trang Hwy Bridge over	16 Apr 65	Initial strike. One of two channel spans dropped, little pier damage; remaining spans
175730N 1054855E		Rao Cai		in good condition.
103,203922	25X1	340 x 10 ft.: 4-span, steel half-thru	8 May 65	No change in bridge status. Ford bypass serviceable.
25X1		truss on concrete piers	3 Jun 65	Restrike. Heavy damage to planking.
20/(1			15 Jun 65	No change; bridge unserviceable.
			17 Jun 65	Restrike. Bridge unserviceable; road cratered.
	*		22-27 Jul 65	Bridge unserviceable; ford serviceable.
	8. (•	23 Aug 65	No change.
•			7 Sep 65	Restrike. Northwest span damaged; ford cratered.
	•		23 -27 Sep 65	No change.
		*	27 Oct - 8 Nov 65	No change; ford serviceable.

Location	Target Number	Name		Date	Status
			y +	10 Oct 65	Restrike. No significant damage. Alternate bridge crossing still under construction. Estimated 4-span, concrete deck-type design. Eypass ford still in good condition.
		•		18 Oct - 2 Nov 65	Bypass ford submerged. New ford appears installed west of target bridge.
	• .	,		27 Oct • 17 Nov 65	Target bridge still unserviceable. Temporary repairs deteriorated. Alternate bridge crossing still under construction.
	. *		• s	29 Nov 65	Restrike. North approach cratered. Alternate bridge still under construction.
3			· ·	13-16 Dec 65	Alternate bridge still under construction. Eypass ford serviceable.
	•	*		23 Dec 65	Restrike. Further damage to couth end of original target bridge. No reported damage to alternate bridge.

SECRET

TAB C- HIGHWAY BRIDGES

Location	Target Number	Name	Date	Status
Route 18		Ha Chanh Hwy Bridge over	28 Nov 65	Initial strike. 115 ft center span dropped; south approach cratered. Ford or ferry
210724N 107 2105E		stream.		bypass west of bridge cratered; was under construction prior to strike.
_	25X1	185 x 12 ft.; 3-span, concrete deck-type		

25X1

SECRET

TAB C - HIGHWAY BRIDGES

Location	Target Number	Name	Date	Status
Route 19		Ban Pom Lot Hwy Eridge S. over	3 Jul 65	Unsuccessful - bad weather.
211641N 1030030E	·	Khe Cam Ly	23 Jul 65	Initial strike. Both bridge approaches cratered; possible damage to bridge; unserviceable.
	25X1	260 x 12 ft; 3-span, half-thru steel truss; newly constructed.	24 Jul 65	Partially destroyed south deck. Bridge unserviceable.
25X1		ı•	28 Jul 65	Bridge unserviceable; no repairs.
			29 Jul 65	Restrike. One span dropped. Bridge unserviceable.
	•	•	31 Jul 65	North span severely damaged at abutment. Bridge unserviceable; no repairs attempted.
			2 Aug 65	Restrike. North span, previously damaged, now destroyed. South span and abutment damaged. Seasonal ford at site.
			5 Aug 65	Approaches cratered. Bridge still unserviceable; no repairs noted.
			12 Aug 65	No change since 5 Aug.
		·	17 Aug 65	Bridge unserviceable; ford serviceable.

Approved For Release 2020866 : CIA-RDP78S02149R000100170010-1

SECREY

Location	Target Number	Name	Date	Status
	e		22-25 Sep 65	No Change.
			3-17 Oct 65	No Change.
	•		19 Oct 65	Ford damaged.
			23 Nov 65	Bridge unserviceable; ford serviceable.
			22 Dec 65	No change; bridge unserviceable.

SECRET

Location	Target Number	Name	Date	Status
Route 82		San Dinh Hwy	23 Apr 65	Initial strike. Bridge totally demolished.
182403N		Bridge over Song Kiem		Possible fording site nearby.
1054341E		140 x 11 ft.; 2-span,	7 May 65	Crossing unserviceable except for probable ford. New bridge under construction and
	25X1	concrete deck		realined approaches; estimated 50% complete.
25X1			5 Jun 65	New bridge/causeway serviceable for traffic. Approximately 1 month recovery time.
			26 Jun - 2 Nov 65	Bridge/causeway remains serviceable to light traffic.
•		e ^c	2-9 Nov 65	Possible restrike. Eridge/causeway bypass damaged.

SECRET

Location	Target Number	Name	Date	Status
Route 101		My Duc Hwy Bridge over Khe Cam Ly	20 Apr 65	Initial strike. Bridge serviceable. Minor damage; approaches cratered.
1064215E		190 x 29 ft.; 3-span,	22 Apr 65	Restrike. Bridge unserviceable. 1 span
	25X1	concrete deck-type		demolished, I span dropped; north pier destroyed. South span received superficial damage. South approach severely cratered.
25X1		*	9 May 65	Eridge remains unserviceable. No repairs noted.
	•	*	23 Sep 65	Nearby ford crossing probably in use.
			19 Nov 65	Foot bridge constructed, 500 ft. west of target bridge.

SECRET

Location	Target Number	Name	Date	Status
Route 110		Loc Dien Hwy Bridge over stream	16 Sep 65	Initial strike. One span destroyed, one span severely damaged. Bridge unserviceable.
1062311E	0574	60 x 12 ft.; 3-span, timber deck	29 Sep 65	Damaged span repaired; repairs in progress on destroyed center span. Bridge unserviceable.
	┘ 25X1	type	10 Oct 65	Repairs still in progress on destroyed center span. Bridge remains unserviceable.
25X1			24 Oct 65	Restrike. Bridge destroyed.